

Central Valley School District No. 356

BROADWAY ELEMENTARY

**2006-2007 Annual Public Notice  
Asbestos Hazard Emergency Response Act**

In compliance with the U.S. Environmental Protection Agency (EPA) Asbestos Hazard Emergency Response Act (AHERA), Central Valley School District conducted initial asbestos inspections in each District facility in 1989. Periodic follow-up surveillance and inspections have been performed,

The AHERA Inspection Report/Management Plan (1989) and reports of Reinspection conducted in 1992, 1995, 1998, 2001 and 2004 are available to the public. They can be reviewed any time during normal school hours. As required by AHERA, a designated person is available during regular District office hours to answer any questions concerning asbestos containing building materials (ACBM) in our buildings. The designated person can be contacted through the District office at 228-5400.

The following Non-Friable Asbestos Containing Building Materials are present in the Broadway Elementary School Building:

- Pipe lagging, joints, elbows, and tees (utilidors, attic above gym)
- Vinyl floor tile and adhesive (Rms. 101-108, 201-209, staff lounge, computer lab, stage steps, gym storage, hall, library, pantry, office, staff workroom)
- Sheet vinyl flooring (Rms 201-209,)

The following Friable Asbestos Containing Building Materials are present in the Broadway Elementary School Building:

- None

All ACBM listed above were found to be in good condition and are being continually maintained in accordance with Washington State and Federal laws.